Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

DN571 MAN HOLE # 59865 NY Spills S104953854
ENE BANNER AVE/6TH ST N/A

1/2-1 BROOKLYN, NY

0.861 mi.

4548 ft. Site 2 of 2 in cluster DN

 Relative:
 SPILLS:

 Higher
 Name:
 MAN HOLE # 59865

 Actual:
 Address:
 BANNER AVE/6TH ST

 9 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0100092 / 2001-08-22

Facility ID: 0100092 Facility Type: ER DER Facility ID: 118264 Site ID: 138306 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2001-04-03 Investigator: **JHOCONNE** Not reported Referred To: Reported to Dept: 2001-04-03 CID: 233

Water Affected: Not reported Spill Source: Unknown Affected Persons Spill Notifier: Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0 2001-04-03 Date Entered In Computer:

Date Entered In Computer: 2001-04-03

Spill Record Last Update: 2001-08-22

Spiller Name: Not reported

Spiller Company: UNK

Spiller Address: Not reported

Spiller Company: 999

Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

O'CONNELL "

Remarks: "con ed # 136232 unk oil lab results show 170 ppm pcb clean up will

start tomorrow am spill on 200 gallons of water confined in manhole

no to all 5 questions "

All Materials:

 Site ID:
 138306

 Operable Unit ID:
 837153

 Operable Unit:
 01

 Material ID:
 555679

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

Oxygenate: Not reported